



COMMONWEALTH
OF VIRGINIA

STATE WATER CONTROL BOARD

ORIGINAL
(Red)

EXECUTIVE SECRETARY
L. H. PARSONS

P. O. BOX 11143 - RICHMOND, VIRGINIA 23230 - (721) 774-2341

PLEASE REPLY TO: TIDEWATER REGIONAL OFFICE
P. O. BOX 485, GLOUCESTER POINT, VA. 23062
(TELEPHONE: 642-2144)

BOARD MEMBERS

W. P. GRIFFIN
HENRY S. HULLAND
W. H. SINGLETON
ROBERT W. SP. 1984
E. BLANCHARD MOORE
CHAIRMAN

August 21, 1969

Mr. R. L. Brandt & Sons
P. O. Box 6
Yorktown, Virginia

Dear Mr. Brandt:

As a result of a recent investigation by our staff of your fly-ash disposal area near Seaford, it has been determined that the present dykes have suffered considerable erosion during heavy rains. This fly-ash is flowing from your disposal area, into the head waters of Chisman Creek. There is some evidence that this material is accumulating in the channels of Chisman Creek.

Such a discharge of this material into State waters, as stated in the Water Control Law, is a violation of this law, a copy of which is enclosed. You are therefore requested to make all necessary repairs to the dykes around the present disposal area, to prevent this fly-ash from reaching State and local waters.

You are also requested to submit to this office, a full description of the repairs made, and to keep the dykes under such repairs as to prevent any future discharges.


Your cooperation in this matter will be greatly appreciated.

Very truly yours,

G. T. Yagel, Tidewater
Regional Representative

STY/nls

cc: Mr. R. L. White
Dr. Morris Graham, V.I.P.S.
Mr. J. R. Stock - V.E.P.C.O. Power Station, Yorktown
State Water Control Board; Richmond Office, Tidewater Office



AR100036